

TECHNICAL INFORMATION

SEIKO EPSON CORP,Printer Technical Support Grp

H/W SUPPORT
MANUAL/STK
GENERAL

S/W,F/W SUPPORT
AS-TOOL

Authorized by / M.Kawada, Mgr
Approved by / Y.Asakawa, AstMgr
Issued by / Hiroshi Misawa

<<URGENT>>

Please take immediate action with highest priority

<<IMPORTANT>>

Please make sure all necessary actions are taken care of

<<CONFIDENTIALITY RANK>>

Rank S

Rank D

Rank

U

(ESC/Internal only)

(open to dealers)

(Public)

Model : Stylus Photo 895/PhotoPC 3100Z

SUBJECT : EPSON PhotoQuicker3.0 Patch File Rev.3.0pE

Description

1. Modified items

[Addition]

1) Supporting WindowsXP.

[Bug modification]

The following bug is modified.

1) When the customer enter "2 bytes" character code with using ATOK, entered character is not displayed.

2. Disk contents

Disk name : EPSON PhotoQuicker3.0 Patch File

Disk Rev. : 3.0pE

Software :

Windows : Ver.3.023

Service Report No. None

S/B Issue: No Yes (S/B No. P-)

Distribution:

EAI(APSP) EAI(DOC) EAI(LATIN) EASA EDB ECSA ECOL ECOR EMSA
EPSA EVSA EITC EPI EDG EUL EFS EIS EIB EAL EHK ESP ETT
EEB ETH EMO EKL ECC EEF EID EPC ESIE EPO

3. Using Environments

No.TE01-251 Rev.A

Date : October 3, 2001 2/2

OS : WindowsXP

PC : IBM or IBM compatible PC

4. Others

- 1) Attached data (CD-ROM 1 piece) with this information.
- 2) This data is released as Patch File of the Stylus Photo 895 and PhotoPC 3100Z for the Customer Support.
- 3) This data is used for EAL/EHK/ESP/EUL.
- 4) How to install the Patch File.

Please execute installation with the following step.

[Windows]

Execute "Setup.exe" in EPSON PhotoQuicker3.0 Update folder.