

User's Guide Update

For Windows 98 users

When you install scanner software on Windows 98, the EPSON TWAIN 3 Setup dialog box and EPSON Screen Calibration utility dialog box may not appear at the end of Add New Hardware Wizard. These dialog boxes will appear while installing software from EPSON Software Installer dialog box. Proceed as normal in the case that you see these dialog boxes twice.