

Supplement

Please note the following correction to the EPL-N1600 *Reference Guide*.

The Imaging Cartridge's model number is described in your *Reference Guide* is incorrect. Please change the number as follows:

Replace	With
S050012	S051056